

SLOPE PROTECTION



Fall 2023
















In the Fall of 2023 a construction project where the integrity of a slope and the safety of a buried pipeline were at risk due to erosion, weathering, and natural elements, needed a permanent and robust solution. The need to protect both the slope and the buried pipeline prompted the consideration of Concrete Canvas CCT2™ as a viable solution. CCT2™ was proposed to cover and safeguard the slope and pipeline, mitigating the risks posed by environmental factors.

Five bulk rolls of CCT2™ were utilized for the project, strategically laid out longitudinally to provide comprehensive coverage. The installation process required thorough planning and execution to ensure effective slope protection and pipeline covering.

Utilizing CCT2[™], the project successfully addressed the challenges posed by erosion, weathering, and other natural elements, providing robust protection for the slopes and pipelines.

By laying the rolls longitudinally, comprehensive coverage was achieved, minimizing the risk of vulnerabilities or gaps in protection. The CCT2™ material formed a durable barrier, safeguarding the slope and the buried pipeline from external threats.















