

CASE STUDY

Pond Lining- Soil Treatment Facility

- **LOCATION:** Inuvik, Northwest Territories
- **PROJECT TYPE:** Product Installation
- **PRODUCT USED:** 60mil HDPE Single Sided Textured Geomembrane

BACKGROUND:

Two ponds in Inuvik, Northwest Territories were being constructed at a soil treatment facility. These ponds needed to be lined with geomembrane liner per environmental protection requirements. This project was being executed at the onset of the pandemic an there were no experienced installers in the area.

ACHIEVEMENT:

Titan was contacted to provide a field crew with the necessary expertise to complete the lining project.

We stepped up to the plate and sent an experienced crew to this remote location, alleviating a major challenge for the General Contractor. Our involvement resulted in the successful completion of the ponds and helped the contractor execute this construction project on schedule.

Contact us for more information:

TITAN ENVIRONMENTAL CONTAINMENT

Toll free: 1-866-327-1957 | Email: info@titanenviro.com | Web www.titanenviro.com

TRUST.QUALITY.VALUE