



August 2021



CC5™ Batched



10 Rolls



Transverse and
longitudinal



North West
Alberta, Canada



CNRL



Remediation



In August 2021, local contractors installed 91m² of Concrete Canvas® (CC5) to rehabilitate an existing tank farm on a concrete pad. The soil surrounding the tank farm was eroding and starting to undermine the concrete pad so CC5™ was chosen as a hard armor erosion protection solution

Before laying the CC rolls, the installation team walked around the pad and filled in all the areas where the soils had eroded, then packed the fill down. CC rolls were then laid under all the piping and existing equipment, and attached to the concrete pad.

The tight working area and the need to work around existing infrastructure made this a detailed task, however, CC's portable batched rolls and the fact that this product can be installed without the use of heavy machinery made for a seamless installation.

CC5™ laid longitudinal



CC5™ laid transverse under pipe sections

