



CASE STUDY

Irrigation Pond - HDPE Geomembrane



- ▼ **LOCATION:** Barbados, Caribbean
- ▼ **PROJECT TYPE:** Installation Only
- ▼ **PRODUCT USED:** HDPE Geomembrane



▼ **PROBLEM:**

A client required professional installation of geomembrane liner for three irrigation ponds.

▼ **THE TITAN SOLUTION:**

When a contractor contacted Titan to help with the installation of three pond liners at a site in Barbados, we knew we were the right candidate for the job. The ponds were required to store water from the wet season for agricultural crop irrigation during the dry season. With over 23 countries serviced globally and over 1,300 successful installations, Titan is well-equipped with the expertise and experience needed to handle various environmental containment projects.



▼ **ACHIEVEMENT:**

Titan crews and local workers installed over 450,000 SF (41,806 m²) of HDPE geomembrane liner for this project. Titan maintained superb quality control onsite and took extreme safety measures; the team worked diligently to complete the installation in record time.



Contact us for more information:

TITAN ENVIRONMENTAL CONTAINMENT

Toll free: 1-866-327-1957 | Email: info@titanenviro.com | Web: www.titanenviro.com

TRUST.QUALITY.VALUE