
## CONCRETE CANVAS

OUTFALL



A rural municipality in Saskatchewan was seeking to solve a culvert outfall erosion problem as part of a new road construction project. Based on site conditions and needs, our team introduced <u>Concrete Canvas® (CC)</u> batch rolls as the ideal solution, which was then put into action.

We transported the 7 batch rolls of CC directly to the site to line a 343ft<sup>2</sup> (32m<sup>2</sup>) area. Driven by customer satisfaction and our commitment to having the product perform as promised, Titan also provided on-site installation assistance to ensure the material was correctly installed. The installation was completed in one day by four people.

This project is a compelling illustration of Concrete Canvas® as a versatile and reliable solution for erosion control and slope protection. Its unique blend of durability and flexibility proves invaluable in navigating challenging environments, providing a robust defense against erosion and ensuring the stability of structures over the long term.





info@titianenviro.ca



www.titanenviro.com

Canvas Ltd. 2023 Canvas Ltd. 2023